

Service

BULLETIN #129

JULY 2, 1993

PAGE 1/1

MODELS AFFECTED

P-61, P-63

SUBJECT

INSTALLATION OF P60045 RELAY

The P60045 relay receptacle must be installed as illustrated in the installation manual.

Mounting in any other position may cause premature relay failure and or possible engine damage.

When choosing the mounting location take into consideration the relay must be kept away from water and road spray, and that the relay spade terminals must be downwards when entering the relay receptacle.

Pacbrake Service

PACBRAKE[®]
ENGINE & EXHAUST BRAKES

Phone: 800-663-0096 • Fax: 604-882-9278 • E-mail: info@pacbrake.com • Internet: www.pacbrake.com
Canada: 19594 - 96 Ave., Surrey, BC V4N 4C3 • USA: P.O. Box 1822, 250 H St, Blaine, WA 98231-1822