

# Service

## BULLETIN #113

FEBRUARY 14, 1991

PAGE 1/1

MODELS AFFECTED

**P-36, P-36P**

SUBJECT

**NEW SLAVE PISTON SETTING  
FOR 1991 ENGINES**

**Pacbrake Model P-36 and P-36P installations on 1991 3406B Cat engines require a .070" slave piston setting due to a turbo change.**

These engines can be identified by engine serial number prefixes of 2EK and 3ZJ.

Please note these numbers, as manuals in existing stocks will not reflect this change.

The following information shows current PACBRAKE slave piston settings for all 3406 engines.

MODEL	SETTING		
	P-36	P-37	Gauge
3046	.060	N/A	P07446
3406B prior 1991	.080		P34670
		.102	P34675
3406B 1991	.070		P13184
		.102	P34675

**Pacbrake** Service

**PACBRAKE**<sup>®</sup>  
ENGINE & EXHAUST BRAKES