

Service

BULLETIN #166

MARCH 18 2003

PAGE 1/1

MODELS AFFECTED

P-80 and P-80A

SUBJECT

RELEASE OF P01500 CONTROL VALVES IN MODELS P-80 AND P-80A

Pacbrake has released the use of P01500 control valves in all P-80 and P-80A engine brakes.

The control valve part number P01500 replaces the previously used part number P11930.

The P01500 control valve will be used with inner control valve spring part number P11435 and outer spring part number P11434. If updating an engine brake to a new combination, it is imperative all cylinders are done. It is not recommended to interchange the new and old combinations in the same engine brake.


These parts are available through the Pacbrake distribution system.

P-80 engine brakes Serial #091788 and later contain the new control valve.

P-80A engine brakes Serial #098259 and later will contain the new control valve.

This is a product improvement not subject to campaign.

Old Combination New Combination



Pacbrake Service

PACBRAKE[®]
ENGINE & EXHAUST BRAKES

Pacbrake Company

toll-free: 800-663-0096 phone: 604-882-0183 fax: 604-882-9278 e-mail: info@pacbrake.com Internet: www.pacbrake.com

Pacbrake exhaust brakes are protected by law. U.S. patents 5,445,248. Patents pending. Pacbrake and Direct Mount are registered trademarks of Pacbrake Company. Other trademarks used herein are property of their respective holders. Printed in Canada #166
Last Revised: 19/12/03